

REPORT of SURVEY for REPAIRS, &c.

No. *6185*

(Received at London Office) Rec'd 24 JULY 1883

No. in Survey held at *Glasgow* Date, first Survey *July 19th* Last Survey *July 21* 1883
 Reg. Book. *Iron S.S. "Ethelbert"* (No. of Visits) *3* Master *C. Smith*

469 on the
 TONNAGE under Tonnage Deck
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *51.3*
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. *32.3*

Built at *Belfast* When built *1881*
 Owners *Colvil, Lowden & Co* Port belonging to *Glasgow*
 Residence *45 Buchanan Street Glasgow*
 By whom built *Workman, Clark & Co* Destined Voyage *Bilboa*
 If Surveyed Afloat or in Dry Dock (State Name of Dock)

Length of Poop *38* ft. Ditto, Forecastle *38* ft. Ditto, Raised Quarter Deck *80* ft.
 Years assigned. *100A1* Character in Register Book.
 Classed *100A1*

Last Survey, No. *4724* Port *Lth* Society's Freeboard (if assigned) as painted on Ship *5-83*

REPAIRS, OR EXAMINATION AS PER RULE Cause of Repairs to be clearly stated. *Checking the Load-line*

State dates of any letters respecting this case

*In compliance with the request of the owners the freeboard has this day been correctly marked on the sides of the vessel in accordance with the terms of the Secretary's letter of 11th July and as shown in Notice No 471**

*Freeboard in Salt water 1ft 4 in
 do do Fresh do 1ft 1 in*


Present Condition of the			
Decks	} <i>Not seen</i>	Treenails	} <i>Not seen</i>
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	
Planksheers		Keelsons	
Sheerstrakes		Clamps and Shelves	
Topsides		Ceiling	
Wales		Rudder	
Plank (Bottom) and Counter		Copper (or Y.M.) When put on (State if on Felt.)	
Engine Room Skylights	Cement (if Iron Ship)	Windlass and Capstan	} <i>Not seen</i>
Coal Bunker, Openings, Lids, &c.	Caulking of Bottom, Deck, & Waterways	Pumps	
Scuppers		Boats	
		Masts, Yards, &c.	
		Condition, how ascertained	
		Sails	
		Anchors No. of	
		Cables	
		Hawsers and Warps	
		Standing & Running Rigging	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	Hatches

14.⁰
1.4

The Amount of Entry Fee ... £ : : received by me, }
 Special ... £ 0 : 0 : 0 188 }
 Certificate (if required) } £ : :
 to be sent as per margin... }

G. S. Hindmarsh
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *FRIDAY 27 JULY 1883*
 Character assigned *Note the freeboard*



Form No. 2 for Repairs.—1,000—9/7/83. (If a Steam Ship, state whether or not a Report is also sent on the Machinery.) (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Insert Character precisely as in Register Book.)