

ANNUAL SURVEYS

(Received at London Office.)

MONDAY 22 OCT 1883

No. 6286 Survey held at Glasgow Date, first Survey 2 Oct. Last Survey 2 Oct. 1883
 No. in Reg. Book. 432 on the Steel S.S. "Glydeadale" Master W. Johnstone
 Net 600 Built at Port Glasgow When built 1881 10 Month.
 Gross 972 By whom built Blackwood & Gordon Owners R. Mackill & Co.
 Under Dk. 730 Port belonging to Glasgow Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Inglis's slip
(State Name of Dock.)

Last Survey, No. 5915 Port of Gls Classed 100A.1.
 Years assigned. 11.82 Character in Register Book.

Present Condition of the Decks <u>good</u>	Treenails <u>good</u>	Breasthooks and Stemson <u>good</u>
Waterways	Transoms, Pointers, and Crutches	Windlass and Capstan <u>good</u>
Comings	Timbers of the Frame at the Openings	Pumps
Upper Deck Beams & Fastenings	Ditto ditto at other places	Boats
Lower Deck Beams & Fastenings	Keelsons	Masts, Yards, &c.
Planksheers	Clamps and Shelves	Condition, how ascertained <u>from deck</u>
Sheerstrakes	Ceiling	Sails <u>good</u>
Topsides <u>Plating</u>	Rudder	Anchors, No. of <u>3 B. 1 S. 2 H.</u>
Wales	Copper or Y.M. <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>	Cables <u>said to be complete</u>
Plank (Bottom) and Counter	Caulking of Bottom, Deck, & Waterways <u>good</u>	Hawsers and Warps <u>good and</u>
Engine Room Skylights <u>good</u> Coal Bunkers, Openings, Lids, &c. <u>good</u> Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>		Standing and Running Rigging <u>sufficient</u>

General Observations, Opinion as to Class, &c.
*The bottom of the vessel cleaned and recoated.
 This vessel is now in good and efficient condition and is eligible in my opinion to remain as classed.*

Committee's Minute TUESDAY 23 OCT 1883 18 Surveyor G. Stanbury
 Character assigned TBW 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 6286 Survey held at Glasgow Date, first Survey Oct 15th Last Survey Oct 14th 1883
 No. in Reg. Book. 814 on the Iron S.S. "Clan Buchanan" Master E. N. Collett
 Net 1913 Built at Dumbarton When built 1882 2 Month.
 Gross 2933 By whom built A. McMillan & Sons Owners Hayden, Irvine & Co
 Under Dk. 2662 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Govan dry dock
(State Name of Dock.)

Last Survey, No. 6156 Port of Gls. Classed 100 A1 5-82
 Years assigned. Character in Register Book.

Present Condition of the Decks <u>Good</u>	Treenails <u>Good</u>	Breasthooks and Stemson <u>Not seen</u>
Waterways	Transoms, Pointers, and Crutches	Windlass and Capstan <u>Good</u>
Comings	Timbers of the Frame at the Openings	Pumps
Upper Deck Beams & Fastenings	Ditto ditto at other places	Boats <u>6</u>
Lower Deck Beams & Fastenings	Keelsons	Masts, Yards, &c.
Planksheers	Clamps and Shelves	Condition, how ascertained <u>from the dock</u>
Sheerstrakes	Ceiling	Sails
Topsides	Rudder	Anchors, No. of <u>3 B. 1 S. 2 H.</u>
Wales	Copper or Y.M. When put on	Cables <u>complete</u>
Plank (Bottom) and Counter	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Hawsers and Warps <u>Sufficient</u>
Engine Room Skylights <u>Good</u> Coal Bunkers, Openings, Lids, &c. <u>Good</u> Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches <u>Good</u>		Standing and Running Rigging <u>Efficient</u>

General Observations, Opinion as to Class, &c.
*The bottom of the vessel cleaned and recoated.
 A few rivets aft renewed in garboard plate, and the edges of the plate caulked.
 This vessel is now in good and efficient condition and is eligible in my opinion to remain as classed.*

Committee's Minute TUESDAY 23 OCT 1883 18 Surveyor G. S. Hindmarsh
 Character assigned TBW 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 4 for Annual Survey, when there are no repairs. 4000-617/80.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)



GLS148-0276