

# REPORT of SURVEY for REPAIRS, &c.

(Received at London Office) MONDAY 17 DEC 1893

No. *6763*

No. in Reg. Book *15* Survey held at *Glasgow* on the *Iron S.S. Queen*

Date, first Survey *4<sup>th</sup> Dec 93* Last Survey *4<sup>th</sup> Dec 93* (No. of Visits *3*)

Master *A. Wilson*

Official Number  
 Tonnage under Tonnage Deck *271*  
 Ditto of Spar Deck, or Avning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage *204*  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St' mer, cut on Bm. *170*

Built at *Glasgow* When built *1857*  
 Owners *W. MacIlwraith* Port belonging to *Dundee*  
 Residence *Rouffern*  
 By whom built \_\_\_\_\_ Destined Voyage *Coen*  
 If Surveyed Afloat or in Dry Dock *Afloat*  
(State Name of Dock)

Length of Poop \_\_\_\_\_ ft. Ditto, Forecastle \_\_\_\_\_ ft. Ditto, Raised Quarter Deck \_\_\_\_\_ ft.  
 Years assigned \_\_\_\_\_ Character in Register Book \_\_\_\_\_

Last Survey, No. *2508* Port *Fab* Classed *100 A.1.*  
*S.S. No 3-36* *5:83.*

REPAIRS, OR EXAMINATION AS PER RULE  
 Cause of Repairs to be clearly stated. Society's Freeboard (if assigned) as painted on Ship  
*S.S. No 1-180*

State dates of any letters respecting this case \_\_\_\_\_

*Please see Falmouth Report No. 2508, and Secretaries' letters dated 29<sup>th</sup> Nov. and 7<sup>th</sup> Dec. in reference to the completion of the equipment of this vessel. A new main sail now supplied. The deck pump in the engine room has been overhauled and repaired here.*

Present Condition of the			
_____	Treenails	_____	Windlass and Capstan
_____	Breasthooks and Stemson	_____	Pumps
_____	Transoms, Pointers, and Crutches	_____	Boats
Deck Beams & Fastenings	Timbers of the Frame at the openings	_____	Masts, Yards, &c.
Deck Beams & Fastenings	Ditto Ditto at other places	_____	Condition, how ascertained
_____	Keelsons	_____	Sails <i>good &amp; sufficient.</i>
_____	Clamps and Shelves	_____	Anchors No. of _____
_____	Ceiling	_____	Cables
_____	Rudder	_____	Hawsers and Warps
_____	Copper (or Y.M.) When put on _____	_____	Standing & Running Rigging
_____	(State if on Felt.)	_____	Cargo and Main Hatchways
Bottom) and Counter	Cement (if Iron Ship)	_____	Hatches
Room Skylights	Caulking of Bottom, Deck, & Waterways	_____	
Coal Bunker, Openings, Lids, &c.	Scuppers	_____	
Observations, Opinion as to Class, &c.			

*In connection with Falmouth report No. 2508, dated Nov. 1893, the above remarks are submitted for the information of the Committee.*

The Amount of Entry Fee ... £ : : received by me, }  
 Special ... £ : : 188 }  
 Certificate (if required) } £ : :  
 to be sent as per margin... }

*G. Stanbury*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £ \_\_\_\_\_)

TUESDAY 18 DEC 1893

Committee's Minute  
 Character assigned *JBM 100 A.1*  
*5:83 as See Falmouth No 2508*

Form 9. The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.