

REPORT of SURVEY for REPAIRS, &c.

4/148
THUR. 15 OCT 1885

No. 4148

No. in Reg. Book. Survey held at Glasgow Date, First Survey 6th Sept. Last Survey 7th Oct^r 1885
(No. of Visits 2)

436 on the Iron S. Francis Thorne Master J. Mc Cormack
YEAR. MONTH.

TONNAGE: Built at Blackburn By whom Richardson Duck When 1868
NET 1297 Owners J. R. Dickson Port belonging to Glasgow

GROSS 1346 Owner's Address (if not already recorded in Appendix to Register Book.)
UNDER DK. 1200

Surveyed Afloat in Dry Dock Afloat Name of Dock Queen's dock Destined Voyage Sydney

Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 1323 Port Dub Classed Years assigned, if a Wood Ship. * A. 1.

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
in salt water _____ ft. _____ ins.
in fresh water _____ ft. _____ ins.

REPAIRS, OR EXAMINATION AS PER RULE

With reference to Dublin Report No. 1323, and the Secretary's letter of 5th inst (M) the pressing repairs and boats referred to are made good as recommended.
The vessel has been measured for freeboard as directed and she sailed from this port on the 10th inst. The report on the freeboard measurements has been forwarded for the consideration of the Committee.

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, &c. :
In connection with the above see the accompanying report by the surveyor at Dublin No. 1323

Entry Fee (if chargeable) per Scale I., Sec. 27.	£	:	:	
Office Fee (if chargeable) per Scale II., Sec. 27.	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

received by me, 188

G. Stanbury
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned [Signature] FRIDAY 16 OCT 1885

* If a Steam Ship, state whether or not a Report is also sent on the Machinery

* Insert Character precisely as in Register Book.

Form No. 2 for Repairs—2000—16/5/85—Transfer Ink. The Surveyors are requested not to write on or below the space for Committee's Minute.