

Report of Survey for Repairs, &c., of Engines & Boilers.

No. *4148* (Received at London Office, MONDAY 2 Nov 1885)
 No. in Reg. Book. *292* Survey held at *Glasgow* Date, first Survey *22nd Oct^r* Last Survey *24th Oct^r* 188*5*
 on the Machinery of the *S. S. Lennox* (Number of Visits *3*)
 Tonnage, Gross *2051* Built at *Glasgow* When built *1880* 6th Month
 Ditto, Net *1327* Owners *J. Warrack* Port belonging to *Leith*
 Diameter of Cylinder *38 & 68* Engines made by *A. Stephen & Sons* When made *1880*
 Length of Stroke *45* Boilers made by *Do* When made *1880*
 Pressure of Steam *85 lbs* If Surveyed Afloat or in Dry Dock *Both Henderson Dock* Character in Register Book.
 Registered Horse Power *240* (State name of Dock.) *Classed 100A. 6-85*
 Last Survey No. *240* Port *Leith* *+ L.M.C. 7-84*

Particulars of Repairs and Examination *Annual Survey*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

The machinery of this vessel opened out for survey and there were examined the cylinders, pistons, slide valves, crankshaft, pumps, pipes & also the main & donkey boilers, safety valves & connections.

When the vessel was in dry dock the sea cocks & valves, propeller & were all examined. Propeller shaft removed and outer bearing in stern tube re-filled with wood. Donkey boiler re-lubed. New gland for 46 P. slide valve rod, also glands for 46 P. piston rods top & bottom.

PRESENT

Decks

Water

Coal

Oil

General Observations, Opinion, and Recommendation :—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

The machinery of this vessel is in my opinion in good & safe working condition and eligible to be noted *+ L.M.C. 10-85* in the Register Book.

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ *3 : 3* -
 Special Damage Fee (per Section 28) £ : :
 Certificate (if required) £ : :
 Travelling Expenses (if chargeable) £ : :

received by me
30/11/85

Walter E. Robson
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute Tuesday, November, 3rd 1885.

Assigned

Lloyd's Register
 Foundation

GL5151-0146

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

178 gbs

It is submitted that this vessel is
eligible to have the certification
Lm.b. 10.55 recorded.

124

2/11/85



© 2019

Lloyd's Register
Foundation