

REPORT of SURVEY for REPAIRS, &c.

No. 7454

Received in London Office,

TUESDAY 13 MAY 1886

No. in Reg. Book. Survey held at *Glasgow* Date, First Survey *10 May* Last Survey *10 May* 1886
871 on the *Iron B.S. "Minerva"* Master *Burzell*

TONNAGE:—
NET *427* Built at *Newcastle* By whom *Palmer's Co.* When *1862*
GROSS *676* Owners *Palgrave Murphy & Co.* Port belonging to *London*
UNDER DK. *605* Owner's Address
(if not already recorded in Appendix to Register Book.)

Surveyed Afloat on *in Dry Dock* Name of Dock *Russell's dock* Destined Voyage *Oporto*
Length of Poop *ft.:* of Forecastle *ft.:* of Raised Or. Deck *ft.:* Moulded Depth *ft.* ins. *95A.1.*
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. *7431* Port *GL* *SS. No. 3. '75 SS. No. 2. '83.*
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in salt water *ft. 4.86 ins.*
Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in fresh water *ft. ins.*
of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE

*With reference to Glasgow Report No. 7431, dated April '86. —
the stream anchor and 30 fms. of mooring chain referred to therein
were recovered at Oporto, and have now been examined on board
the vessel and found good.*

PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (If Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Wat'rways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			Hatches
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways

General Observations, Opinion as to Class, &c.:

*The above remarks in conjunction with Glasgow Report
No. 7431, are respectfully submitted for the consideration of the
Committee.*

Survey Fee (if chargeable) per Scale I., Sec. 27. £ *✓* *✓* *✓*
Office Fee (if chargeable) per Scale II., Sec. 27. £ *✓* *✓* *✓*
Survey Fee (per Section 28) £ *✓* *✓* *✓*
Special Damage Fee (if any) (per Sec. 28) £ *✓* *✓* *✓*
Certificate (required to be sent as per margin) £ *✓* *✓* *✓*
Travelling Expenses (if chargeable) £ *✓* *✓* *✓*
Second Surveyor's Fee (if any) £ *✓* *✓* *✓*

received by me

145/1886

G. Stanbury,
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRIDAY 21 MAY 1886