

Report of Survey for Repairs, &c., of Engines & Boilers.

7787

(Received at London Office,

WEDNES. 27 JAN 1887

No. *4484* Port of *Glasgow*
 No. in Survey held at *Do* Date, first Survey *Do* and Last Survey *18th Jan 1884*
 Reg. Book. *633* on the Machinery of the *"Lord O'Neill" S.S.* (Number of Visits *One*)

| | | |
|------------------------------------|--|----------------------------------|
| Tonnage, Gross <i>2753</i> | Built at <i>Belfast</i> | When built <i>1884-5</i> |
| Ditto, Net <i>1816</i> | Owners <i>Irish Shipowners Co. Ltd.</i> | Port belonging to <i>Belfast</i> |
| Diameter of Cylinder <i>37.72"</i> | Engines made by <i>Harland & Wolff.</i> | When made <i>1884</i> |
| Length of Stroke <i>45"</i> | Boilers made by <i>Do</i> | When made <i>1884</i> |
| Pressure of Steam <i>90 lbs</i> | If Surveyed Afloat or in Dry Dock <i>Hendersons Dry Dock</i> | Classed <i>100A.1 3-85</i> |
| Registered Horse Power <i>350</i> | (State Name of Dock.) | <i>+ L.M.C. 7-84.</i> |

Last Survey No. _____ Port _____

Particulars of Repairs and Examination

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

When this vessel was in Dry Dock the sea cocks & valves, propeller & fastenings were all examined. Engines & boilers not prepared for survey.

General Observations, Opinion, and Recommendation :—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

The above mentioned parts were found to be in good & safe working condition and I am of opinion the machinery of this vessel is eligible to remain as classed in the Register Book.

| | |
|--|-----------------------|
| Office or Registration Fee (per Sec. 27) £ — : — | } received by me, 188 |
| Survey Fee (per Section 28) £ — : — | |
| Special Damage Fee (per Section 28) £ — : — | |
| *Certificate (if required) £ — : — | |
| Travelling Expenses (if chargeable) £ — : — | |

Walter E. Robson.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute _____

FRIDAY 28 JAN 1887

Assigned _____



© 2019

Lloyd's Register Foundation

GLS153-0083

Insert Character of Ship and Machinery precisely as in the Register Book.

7787 eph.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this vessel
is eligible to remain as classed

D.P.

LS/1/12



© 2019
Lloyd's Register
Foundation

Report of Survey for Repairs, &c., of Engines & Boilers

TO WRITE