

REPORT of SURVEY for REPAIRS, &c.

8143

No. 8143 Port of Glasgow Received in London Office, MONDAY 17
 No. in Reg. Book. 393 Survey held at Glasgow Date, First Survey 26th Sept Last Survey 28th Sept 1887
 (No. of Visits 2)

on the S. S. Glenartney Master Mackinlay 1883-85
 TONNAGE:— NET 1400 Built at Glasgow By whom Ron & Glas Co. When 1873
 GROSS 2143 Owners Mr. Gregor, Gov. & Co. Port belonging to Glasgow
 UNDER DK. 2065 Owners' Address _____
 (if not already recorded in Appendix to Register Book.)

Surveied ~~Afloat~~ or in Dry Dock _____ Name of Dock Govan Destined Voyage Singapore
 Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 46957 Port London S.S. Ron. 8-3-85 12.88
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
 Society's Freeboard (if assigned) in Summer 5 ft. 7 ins. in Winter _____ ft. _____ ins.
 as painted on Ship

REPAIRS, OR, EXAMINATION AS PER RULE, FOR
The bottom cleaned and recoated, and the chain cables ranged. Shru of the rudder pintles renewed and the lower one rebushed. Two life boats repaired.

PRESENT CONDITION OF THE	Plank (Bottom) & Counter	Ceiling	Boats
Decks <u>Good</u>	<u>Good</u>	<u>Good</u>	<u>Good</u>
Waterways	Transoms or Rivets	Rudder	Masts, Yards, &c.
Stowings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained <u>From deck</u>
Up'r Dk. Beams & Fastenings	Transoms, Pointers , & Crutches	Pumps	Sails <u>Good</u>
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of <u>3 B. 1 S. 2 K.</u>
Plank sheers	ditto ditto at other places	Caulk'ng of Bot'm, D'k, & Watrwy's	Cables <u>300 fms. Good</u>
Deerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Top-sides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers <u>Good</u>	Cargo & Main Hatchways <u>Good</u>
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :
This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

	£	:	:	Fees received by me, 188
Entry Fee (if chargeable) per Scale I., Sec. 27...				
Office Fee (if chargeable) per Scale II., Sec. 27...				
Survey Fee (per Section 29)				
Special on Damage, Fee (if any) (per Sec. 28)				
*Certificate (if required) to be sent as per margin				
Travelling Expenses (if chargeable)				
Second Surveyor's Fee (if any)				

J. Thomson
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____ TUESDAY 18 OCT 1887
 Character assigned 100A1
1887

Form No. 3 for Repairs—book—21 3/8 The Surveyors are requested not to write on or below this page.

Insert Character precisely as in Register Book.

