

REPORT of SURVEY for REPAIRS, &c.

No. 8638

Date of Writing Report

188

Port of Glasgow

Received in London Office

JULY 1888

No. in Reg. Book.

Survey held at

Glasgow

Date, First Survey

21 June

Last Survey

6 July 1888

287

on the

Iron Bt. "Don"

Master

Haywood

YEAR.

MONTH.

TONNAGE:—

NET

1115

Built at

Port Glasgow

By whom

Russell & Co

When

1885-12

GROSS

1168

Owners

P. McFarlane

Port belonging to

Port Glasgow

UNDER DK

1070

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Afloat Name of Dock

Destined Voyage

Sydney

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Classed

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No.

47234 Port Don

100 A.1

5.8

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

in Summer

ft.

ins.

in Winter

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR in Completion of survey held at Fremont

Now put on board 90 Fath 3/4 Steel hawser 26 tons supplied by Thefourrock Rope Co 15 - 11 humps.

PRESENT CONDITION OF THE

Decks

Waterways

Comings

Up'r Dk. Beams & Fastenings

Low'r Dk. Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) & Counter

Treenails or Rivets

Breasthooks and Stemson

Transoms, Pointers, & Crutches

Timbers of Frame at the opening

Ditto ditto at other places

Keelsons

Clamps & Shelves

Ceiling

Rudder

Windlass & Capstan

Pumps

Cement (if Iron Ship)

Caulking of Bot'm, D'k, & Watrways

Copper, or Y.M.

(State if on Felt.)

When put on

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers & Warps

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo & Main Hatchways

Hatches

General Observations, Opinion as to Class, Recommendation, &c.:

The above specified hawsers have now been examined on board as requested by the Fremont Surveyors in Completion of survey recently held there

Entry Fee (if chargeable) per Scale I., Sec. 27...

£

Office Fee (if chargeable) per Scale II., Sec. 27...

£

Survey Fee (per Section 28) .....

£

Special on Damage, Fee (if any) (per Sec. 28) .....

£

\*Certificate (if required) to be sent as per margin

£

Travelling Expenses (if chargeable) .....

£

Second Surveyor's Fee (if any) .....

£

Fees applied for,

188

Received by me,

188

Committee's Minute

Character assigned

100 A.1

6/88

on Sub ref No 9525

Surveyor to Lloyd's Register of British & Foreign Shipping.

Lloyd's Register

GLS155-0420