

REPORT of SURVEY for REPAIRS, &c.

8813
10 OCT 88

No. 8813 Date of Writing Report 1888 Port of Glasgow Received in London Office, 10 OCT 88

No. in Reg. Book 29 Survey held at Glasgow Date, First Survey 1st Oct Last Survey 12th October 1888
 (No. of Visits 4)
 on the Iron B. Carl Rosebery Master Frampton
 YEAR. MONTH.

TONNAGE: — Built at Port Glasgow By whom Russell & Co When 1885 . 3
 NET 1121 Owners W. J. Crawford Port belonging to Glasgow
 GROSS 1174 Owners' Address Greenock
 UNDER DEK 1072 (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Afloat Name of Dock Queeris Destined Voyage Hobbourne

Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Or. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
 (if these particulars are not yet recorded in the Register Book.)

Classed 100A1

Last Survey, No. 9584 Port Greenock

State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard } in Summer _____ ft. _____ ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) } as painted on Ship } in Winter _____ ft. _____ ins.
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of survey held at Greenock

In lieu of the test lower took the following now put on board

1645	34.2.6	32.0.0.0	Tested by E. Seathouse, Glasgow
------	--------	----------	---------------------------------

(1068. new) Indorsement on test certificate "one of the above 12860 } 9 lengths of cable has been tested to break strain at this establishment today 9/10/88. E. Seathouse Glasgow

90 Fathoms of 5 1/2 hawser and several coils put on board.

PRESENT CONDITION OF THE	Plating	Blank (Bottom) & Counter	Keelsons	Clamps & Shelves	Coal Bunker, Openings, Lids, &c	Scuppers	Cargo & Main Hatchways	Hatches
Decks <u>good</u>								
Waterways <u>"</u>								
Comings <u>"</u>								
Dk. Beams & Fastenings <u>"</u>								
Light Dk. Beams & Fastenings <u>"</u>								
Sheers <u>"</u>								
Strakes <u>"</u>								
Stowage <u>"</u>								
Water <u>"</u>								
Engine Room Skylights <u>"</u>								

General Observations, Opinion as to Class, Recommendation, &c. :
These named parts of equipment have now been examined onboard in completion of survey held at Greenock

Survey Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 188
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	Received by me, 188

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 10 OCT 1888

Character assigned 100A1 9.88 m L.R. 9584

Form No. 2 for Repairs—1888—14/188.
 The Surveyors are requested not to write on or below