

REPORT of SURVEY for REPAIRS, &c.

No. 8818

Date of Writing Report

188

Port of

Glasgow

Received in London Office,

12 OCT. 81

No. in Reg. Book.

Survey held at

Glasgow

Date, First Survey

Last Survey 10 Oct 1888

1888

on the

Sewer "Conquistador"

Master F. Vines

TONNAGE:-

Built at Dumbarton

By whom A. McMillan & Co.

When 1888

YEAR.

MONTH.

NET 933

Owners Perez Hermanos & Maycas

Port belonging to Valencia

GROSS 1342

Owners' Address Valencia

UNDER DEK. 1215

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock afloat Name of Dock

Destined Voyage Spain

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins. (if these particulars are not yet recorded in the Register Book.)

Classed

100 A 1

Last Survey, No. 8804 Port

Glasgow

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR upon assignment of Freeboard

My Committee's Memo of 29th March 1888. This vessel was assigned a freeboard of 3. 12 in summer and 3. 4 in winter. with a 2. 9 1/2 fresh water mark - these being subject to the dimensions and particulars supplied by the builders being verified on the vessel's completion.

As stated in Glasgow Freeboard survey Report No 8804, dated 1st October 1888. these particulars were verified and consequently the freeboard assigned by the Committee, as above, has been marked upon the side of the vessel.

PRESENT CONDITION OF THE

Planks	Plank (Bottom) & Counter	Ceiling	Boats
Decks	Treenails or Rivets	Rudder	Masts, Yards, &c.
Stairways	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Trunks	Transoms, Pointers, & Crutches	Pumps	Sails
Upper Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Lower Dk. Beams & Fastenings	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Plank sheers	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Sheerstrakes	Clamps & Shelves	When put on	Standing & Running Rigging
Topside			
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c.:

The freeboard assigned by the Committee having been duly marked upon the sides of the vessel it is respectfully submitted that a freeboard certificate in accordance therewith may be granted to the Owners.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	188
Office Fee (if chargeable) per Scale II., Sec. 27...	£	
Survey Fee (per Section 28)	£	
Special on Damage, Fee (if any) (per Sec. 28)...	£	
*Certificate (if required) to be sent as per margin	£	
Travelling Expenses (if chargeable)	£	
Second Surveyor's Fee (if any)	£	

Fees applied for, 188 Received by me, 188

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Character assigned

TUES 10 OCT 1888

Recd F. Vines



Lloyd's Register Foundation