

# REPORT of SURVEY for REPAIRS, &c.

No. 9500

Date of Writing Report

18

Port of

Glasgow

Received in London Office.

THURS 28 NOV 1889

No. in Reg. Book. Survey held at

Glasgow

Date, First Survey

6<sup>th</sup> Nov

Last Survey 22<sup>nd</sup> Nov 1889

(No. of Visits)

Master R. Jennings

TONNAGE:—

NET 1297

Built at

Glasgow

By whom

Barclay, Curle & Co

When

1872

10

GROSS 2001

Owners

Donaldson Bros

Port belonging to

Glasgow

UNDER DECK 197

Owners' Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Dry

Name of Dock

Jovan

Destined Voyage

Length of Poop

ft.:

of Forecastle

ft.:

of Raised Or. Deck

ft.:

Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No.

923

Port

Glasgow

Classed

S.S. 203. 5.83

100A.1

2001. 6.88

6.88

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

in Summer ft. ins.  
in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Repainting &c.

The bottom examined, scraped & repainted.  
The Rudder pintles lashed  
A shell plate in the starboard bow being found slightly cracked, cause not known, now repaired by means of a doubling plate 4 ft long being riveted outside.

PRESENT CONDITION OF THE

|                              |         |                                  |         |                            |
|------------------------------|---------|----------------------------------|---------|----------------------------|
| Decks                        | Plating | Plank (Bottom) & Counter         | Ceiling | Boats                      |
| Waterways                    | Food    | Treenails or Rivets              | Food    | Food                       |
| Comings                      | ✓       | Breasthooks & Stemson            | ✓       | Masts, Yards, &c.          |
| Up'r Dk. Beams & Fastenings  | ✓       | Transoms, Pointers, & Crutches   | ✓       | Condition, how ascertained |
| Low'r Dk. Beams & Fastenings | ✓       | Timbers of Frame at the openings | ✓       | Sails                      |
| Planksheers                  | ✓       | Ditto ditto at other places      | ✓       | Food                       |
| Sheerstrakes                 | ✓       | Keelsons                         | ✓       | anchors No. of 33. 10. 2k. |
| Topsides                     | ✓       | Clamps & Shelves                 | ✓       | Cables                     |
| Wales                        | ✓       |                                  | ✓       | Porter                     |
| Engine Room Skylights        | ✓       | Coal Bunker, Openings, Lids, &c  | ✓       | Hawsers & Warps            |
|                              | ✓       | Scuppers                         | ✓       | Standing & Running Rigging |
|                              | ✓       | Cargo & Main Hatchways           | ✓       | Hatches                    |

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel appears to be in good condition is in my opinion eligible to remain so classed & to have record of survey for 11.89

|  |   |   |   |
|--|---|---|---|
| Entry Fee (if chargeable) per Scale I., Sec. 27...   | £ | : | : |
| Office Fee (if chargeable) per Scale II., Sec. 27... | £ | : | : |
| Survey Fee (per Section 25)                          | £ | : | : |
| Special on Damage, Fee (if any) (per Sec. 25)        | £ | : | : |
| *Certificate (if required) to be sent as per margin  | £ | : | : |
| Travelling Expenses (if chargeable)                  | £ | : | : |
| Second Surveyor's Fee (if any)                       | £ | : | : |

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

FRIDAY 29 NOV 1889

Character assigned

100A.1

LML 6/12/88

BS 11/89



© 2019

Lloyd's Register Foundation

CLS 158-0340