

# REPORT of SURVEY for REPAIRS, &c.

No. 11549

MON 13 JUN 1892

Date of writing Report 18 When handed in at Local Office 18 Port of Glasgow  
 No. in Survey held at Glasgow Date, First Survey 3<sup>rd</sup> June Last Survey 10<sup>th</sup> June 1892  
 Reg. Book. on the Ship S. S. City of Dundee Master Halley

TONNAGE: Built at Belfast By whom Hartman, Clark When 1870  
 GROSS 342 Owners H. Smith & Sons. Port belonging to Glasgow  
 UNDER DK. 312  
 NET 2612 Owners' Address  
 (If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? By what Name of Dock Govan

Destined Voyage Bombay

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned and expired.	Machinery and Boiler Surveys (including date of N.B., if any).
* 100 A 1.		+ L. M. C. 8.90
5.91		

W.B=D.Ba tons; f tons; uE&B tons; CellDB tons;  
 F.P.T tons; A.P.T tons; M.T tons.

Last Survey, No. 11112 Port GLS

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey

This vessel has been placed in dry dock, a few butts in flat of bottom on each side had the caulking slightly started, these have been recaulked and made good. Bottom recreated

SUMMARY OF DAMAGE REPAIRS: Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE

Decks	Transoms, Pointers, & Crutches	Copper, or Y.M.	Hatches
Waterways	Timbers of Frame at the openings	(State if on Fell.)	Boats
Coamings	Ditto ditto at other places	When put on, Month	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Rudder	Condition, how ascertained
Low'r Dk. Beams & Fastenings	Clamps, Shelves & Stringers	Windlass & Capstan	Sails
Plating	Saving	Pumps	Anchors No. of
Planking	Ceiling	Engine Room Skylights	Cables, length
Rivets	Cement or Asphalt	Coal Bunker, Open'gs, Lids, &c.	(State if now ranged out ready)
Breasthooks & Stemson	Tanks	Scuppers	Hawsers & Warps
	Caulking of Bot'm, D'k, & Wat'rw'ys	Cargo & Main H'tch'w'ys	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is now in a good and efficient condition and in my opinion eligible to remain as classed and to have record of survey 6.92

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,
Survey Fee (per Section 25)	£	18.
Special Damage or Repair Fee (if any) (per Sec. 25.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18.
Second Surveyor's Fee (if any)	£	

\*Is Certificate now required?

Committee's Minute

Character assigned

TUES. 14 JUN 1892

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

GLS165-0178

In a Report also sent new on the Machinery of the Ship. If not, state whether, and when, one will be sent.

\* Certificate to be sent to

Form No. 2 for Repairs, 2015, L.R.P.H. 20,000-24,931, Transfer (Int.) (The Surveyors are requested not to write on or below the space for Committee's Minute.)

N.B.-All alterations in the existing records should be underlined.