

THURSDAY 14 SEP 1893

No. 12445

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 13<sup>th</sup> Sept 1893 When handed in at Local Office 13<sup>th</sup> Sept 1893 Port of Glasgow

No. in Survey held at Troon Date, First Survey 6<sup>th</sup> Sept. Last Survey 6<sup>th</sup> Sept. 1893  
Reg. Book. 304 on the S.S. "Marlay" (No. of Visits) Master A. Irving 1891-91

TONNAGE:-

GROSS 798

UNDER DECK 621

NET 349

Built at Belfast

By whom Workman, Clark & Co. Ltd. When 1890 9

Owners' Address

(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dock?

Name of Dock Troon

Destined Voyage Coasting

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Year Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
* 100 A 1	3, 93	* L.M.C. 9, 90

WB= DBa tons; FPT tons; uE&B tons; Cell DB tons; MT tons.

Last Survey, No. 17069 Port Troon

(Periodical Surveys, when held, must be reported in detail and scriptum in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

Iron work in holds from close ceiling upwards cleaned and recoated.  
The bottom cleaned and recoated and the rudder painted and rebushed.

SUMMARY OF DAMAGE REPAIRS: Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE

Decks	Transoms, Decks, & Crutches	Copper, or Y.M.	Hatches
Waterways	Timbers of Frame at the openings	(State if on Felt.)	Boats
Coamings	ditto ditto at other places	When put on, Month	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Rudder	Condition, how ascertained
Low'r Dk. Beams & Fastenings	Clamps, Shells & Stringers	Windlass & Capstan	Sails
Plating	Salting	Pumps	Anchors, No. of
Planking	Ceiling	Engine Room Skylights	Cables, length
Trunnels or Rivets	Cement (State which.)	Coal Bunker, Open'gs, Lids, &c.	(State if now ranged)
Breasthooks & Stemson	Tanks (State if now tested.)	Scuppers	Hawsers & Warps
	Caulking of Bot'm, D'k, & Wat'r'ys	Cargo & Main H'tch'w'ys	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is in good and efficient condition, eligible in my opinion to remain as classed and to have record of survey, Troon, 9, 93.

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,
Survey Fee (per Section 28)	£	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18
Second Surveyor's Fee (if any)	£	

\*Is Certificate now required?

Committee's Minute

Character assigned

FR 15 SEP 1893

100A

J. Thomson  
Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

GLS168-0069

Is a Report also sent now on the Machinery of the Ship? If not, state whether, and when, one will be sent?

\* Certificate to be sent to

Form No. 2 for Repairs, 200. 1. Part H. - 20,000. - 24, 9, 91. - Transfer Link. (The Surveyors are requested not to affix their names below the space for Committee's Minute.)

N.B. - All alterations in the existing records should be underlined.