

GLS179-0062

B. I. due 10, 97 to be completed on vessels

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

return.
slight repair to main Boiler

It is submitted that this
vessel WILL BE eligible for
the record.

B. I. 12, 97 when the
Donkey Boiler & its safety valves
have been examined & all
safety valves adjusted
under steam

HL
12/12/97

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation