





Lower shaft examined stern bush  
unwooded, some small repairs  
effected to Boiler

It is submitted that  
this vessel is eligible for  
THE RECORD.  
13.19.98

21/9/98

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020  
Lloyd's Register  
Foundation