

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of Glasgow
 No. in Reg. Book Survey held at Glasgow Date, First Survey 7 Last Survey 12th Oct 1898
 on the Wood, Iron or Steel Steamer "Pak Ling" Master H. S. Allen

TONNAGE:—

GROSS 4447UNDER DECK 4243NET 2875Built at BelfastBy whom Hobman, Black & Co When 1885 MONTH 9Owners China Mutual S. Nav. Co. LtdPort belonging to London

Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? by dock Name of Dock Meadowside Destined Voyage China

WB=Cell D B or D B a 125 feet; uE&B 61 feet; F 144 feet;
 total capacity 125 tons. FPT 75 tons; APT 50 tons; MT 25 feet 370 tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1092 Port Glasgow

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

| CHARACTER. For Special Survey, Date of last Survey and of Periodical Surveys. | Years Assigned now expired | Machinery and Boiler Surveys (including date of N.B., if any). |
|--|-------------------------------------|--|
| <u>100 A.1</u> | | <u>4 M.C.</u> |
| <u>9.97</u> | | <u>9.98</u> |

Society's Freeboard (if assigned) as painted on Ship and now revised 6 ft. 6 ins.REPAIRS, OR EXAMINATION AS PER RULE, FOR StackingBottom cleaned, examined andrecoated

SUMMARY OF DAMAGE REPAIRS:—

| | Plates. | Frames. | R. Frames. | Floors. | Beams. | Str. Plates. | Dk. Plates. | Other Items:— |
|---------------------------------------|---------|---------|------------|---------|--------|--------------|-------------|---------------|
| Renewed | | | | | | | | |
| Removed and Faired or Repaired | | | | | | | | |
| Faired or Repaired in place | | | | | | | | |

PRESENT CONDITION OF THE

| | | | |
|---------------------------------|---|--|---|
| Decks <u>good</u> | Stringers <u>good</u> | Engine Room Skylights <u>good</u> | Boats <u>good</u> |
| Caulking of Decks <u>"</u> | Inner Bottom Plating <u>not end</u> | Coal Bunkers, Open'gs, Lids, &c. <u>"</u> | Masts, Yards, &c. <u>"</u> |
| Waterways <u>"</u> | State if Tanks now tested <u>no</u> | Scuppers <u>"</u> | Condition, how ascertained <u>from deck</u> |
| Coamings <u>"</u> | Bulkheads <u>good</u> | Cargo Hatchways <u>"</u> | (State if wedges removed <u>no</u>) |
| Beams & Fastenings <u>"</u> | Ceiling <u>good</u> | Hatches <u>"</u> | Sails <u>good</u> |
| Outside Plating <u>"</u> | Cement on top of <u>not end</u> | Planking of Wood Vessels <u>"</u> | Equipment letter <u>4</u> |
| Caulking of ditto <u>"</u> | (State which.) <u>good</u> | Treenails ditto <u>"</u> | Anchors, No. of <u>30-N-1K</u> |
| Rivets <u>"</u> | Rudder <u>good</u> | Breasthooks & Stemson ditto <u>"</u> | Cables (State if now ranged) <u>no</u> |
| Breasthooks & Crutches <u>"</u> | Windlass <u>"</u> | Transoms, Pointers, & Crutches ditto <u>"</u> | " length (on board) size |
| Transoms <u>"</u> | Have Pumps now been examined and found efficient? <u>not end</u> | Timbers of Frame at openings ditto <u>"</u> | " Rule length (per Table 22) size |
| Frames <u>"</u> | Have Sluice Valves now been examined and found efficient? <u>not end</u> | Ditto ditto at other places ditto <u>"</u> | Hawsers & Warps <u>good</u> |
| Reverse Frames <u>"</u> | Have Watertight Doors now been examined and found efficient? <u>not end</u> | Stringers, Clamps & Shelves ditto <u>"</u> | Standing & Running Rigging <u>"</u> |
| Floors <u>not end</u> | Have Watertight Doors now been examined and found efficient? <u>not end</u> | Salting (State if examined.) ditto <u>"</u> | |
| Keelsons <u>"</u> | Dbing. Plates under Sounding Pipes <u>good</u> | Copper, or Y.M. (State if on felt.) ditto <u>"</u> | |
| | | When put on, Month Year | |

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel is in a good and efficient condition and in my opinion eligible to remain as classed and to have record of survey 10.98

Office Fee (if chargeable) per Scale II., Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) (per Sec. 28.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI, 21 OCT 1898

100A