

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 25-11-98 When handed in at Local Office 18 Port of Glasgow
No. in Reg. Book 113 Survey held at Glasgow Date, First Survey Nov 22 Last Survey 1898
on the Wood, Iron or Steel S.S. "Saint Margaret" Master me

TONNAGE:- Built at Bowling By whom Scott & Co. When 1889 3
GROSS 428 Owners J. Heiton & Co. Ltd. (R. Harper) Port belonging to Dublin
UNDER DEK 249 Owners' Address
NET 178 (if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock? Slipway Name of Dock Madraside Destined Voyage Coasting
WB=CellDBorDBa feet; uE&B feet; J feet; Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons.) precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 16338 Port Gls

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR to further check.

Vessel placed in Slipway Bottom examined, a few rivets in shell renewed and cement repaired, angle for further check renewed. Thwartship beams in hatches repaired

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks	Good	Good	Good
Caulking of Decks	"	Good	"
Waterways	"	"	"
Coamings	"	"	"
Beams & Fastenings	Good	"	"
Outside Plating	"	"	"
Caulking of ditto	"	"	"
Rivets	"	"	"
Breasthooks & Crutches	"	"	"
Transoms	"	"	"
Frames	"	"	"
Reverse Frames	"	"	"
Floors	"	"	"
Keelsons	"	"	"

Stringers	Inner Bottom Plating	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblg. Plates under Sounding Pipes
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shelves	Salting (State if examined.)	Copper, or Y.M. (State if on Felt.)	When put on, Month	Year
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

Boats	Masts, Yards, &c.	Condition, how ascertained	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length (on board)	Rule length (per Table 22)	Hawsers & Warps	Standing & Running Rigging
Good	Good	Inspected	Good	Good	18, 16, 14	Good	Good	Good	Good	Good

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey;" "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel is now in good condition eligible in my opinion to remain as classed and to have record of survey 11, 98.

Office Fee (if chargeable) per Scale II., Sec. 27 £ : : Fees applied for, : :
Survey Fee (per Section 28) £ : : 18 : :
Special Damage or Repair Fee (if any) (per Sec. 28.) £ : : Received by me, : :
Travelling Expenses (if chargeable) £ : : 18 : :
Second Surveyor's Fee (if any) £ : : : :
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned, 100A
TUES. 29 NOV 1893
© 2020 Lloyd's Register Foundation