



WED, 25 JAN 1899

Port of *Glasgow* Continuation of Report No. *16717* dated *18/1/99* on the

*S. S. "Clan Mackay"*

*Repairs - Several started rivets in landing of deep tank top plating renewed and landing edge recutted. To complete S. S. No. 1 - Bunkers to clean and examine examination to be made in boiler space. The owners intend doing this on return from present voyage which will be in about four months time.*

*H. A. J. H.*