

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18. When handed in at Local Office 18. Port of Glasgow
No. in Reg. Book. Survey held at Glasgow Date, First Survey Sept 6 Last Survey Sept 11 1899.
(No. of Visits)

876 on the Wood, Iron or Steel S.S. "Blan Ross" Master Sikson
TONNAGE: Built at Barrow By whom havel for arm. 6° When 1894
GROSS 2622 Owners Gayzer, Irvine & Co. Port belonging to Glasgow
UNDER DECK 2098 Owners' Address
NET 2654 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? By Port Name of Dock Govan Destined Voyage S. Africa
WB=Cellulose DBa 74 feet; uE&B 18 feet; J feet; }
total capacity 100 tons. FPT 97 tons; APT 38 tons; MT 475 feet tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years Assigned	Machinery and Boiler
For Special Survey.	Assigned	Surveys
Date of last Survey and of Periodical Surveys.	not assigned	(including date of N.B., if any).
<u>100 A. 1</u>	<u>4.99</u>	<u>8.98</u>
<u>S.S. Gls. No. 1-98</u>		

Last Report, No. 16947 Port Gls.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified 4 ft. 11 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Locking

Bottom cleaned, examined and recoated. The masts have been taken out and fitted topmasts fitted in lieu of spike topmasts and masts put back

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks <u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>
Caulking of Decks	<u>not end</u>	<u>good</u>	<u>good</u>
Waterways	<u>good</u>	<u>good</u>	<u>good</u>
Coamings	<u>good</u>	<u>good</u>	<u>good</u>
Beams & Fastenings	<u>good</u>	<u>good</u>	<u>good</u>
Outside Plating	<u>good</u>	<u>good</u>	<u>good</u>
Caulking of ditto	<u>good</u>	<u>good</u>	<u>good</u>
Rivets	<u>good</u>	<u>good</u>	<u>good</u>
Breasthooks & Crutches	<u>good</u>	<u>good</u>	<u>good</u>
Transoms	<u>good</u>	<u>good</u>	<u>good</u>
Frames	<u>good</u>	<u>good</u>	<u>good</u>
Reverse Frames	<u>good</u>	<u>good</u>	<u>good</u>
Floors	<u>good</u>	<u>good</u>	<u>good</u>
Keelsons	<u>good</u>	<u>good</u>	<u>good</u>

Stringers	Inner Bottom Plating	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblg. Plates under Sounding Pipes
<u>good</u>	<u>not end</u>	<u>not end</u>	<u>good</u>	<u>good</u>	<u>not end</u>	<u>good</u>	<u>good</u>	<u>not end</u>	<u>not end</u>	<u>not end</u>	<u>not end</u>

Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shelves	Salting (State if examined.)	Copper, or I.M. (State if on felt.)	When put on, Month	Year
<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>

Boats	Masts, Yards, &c.	Condition, how ascertained	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length (on board)	size	Rule length (per Table 22)	size	Hawsers & Warps	Standing & Running Rigging
<u>good</u>	<u>good</u>	<u>by exam.</u>	<u>good</u>	<u>good</u>	<u>3 B. 1 S. 1 K</u>	<u>no</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>	<u>good</u>

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptnd98, &c."

This vessel is in my opinion eligible to remain as classed and to have record of survey 9.99

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,
Survey Fee (per Section 28)	£	18.
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18.
Second Surveyor's Fee (if any)	£	

Committee's Minute
Character assigned

TUES. 19 SEP 1899

100A

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to