

Small repairs to main and
donkey boiler

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. B.S. 11 99.

Remove from limit list

C.M.

30/11/99



© 2019

Lloyd's Register
Foundation

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.