

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office)

TESTS OF BOILER STEEL.

Date first visit 7/9/83 last visit 22/9/83 No. of Visits 2

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

6800-86157-G

£ : :

Surveyor, Lloyd's Register.

H. Andrews

Major, Lloyd's Register,

24/9/83

J. & J. Thomson's No. 104.

Boiler 104



© 2021

Lloyd's Register
Foundation