


Glasgow Report No. 6559.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 1501

(Received in London Office,



TESTS OF BOILER STEEL.

Tests of 1 Steel plate manufactured by The Steel Co of Scotland of Glasgow, Glasgow
 for Boiler No. 308 to be constructed by Messrs M. Paul & Co of Dumbarton
 for Messrs Burrell & Co Ltd S/P No. 29

Date first visit _____ last visit 19/11/83 No. of Visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from the plate with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
								Ins.	Ins.		
1	<u>Dimensions</u> 14 1/2 x 6 1/2 x 3/4	<u>T491</u>		<u>2403</u>	<u>.76</u>	<u>1.16</u>	<u>.881</u>	<u>23.5</u>	<u>26.6</u>	<u>25.5</u>	

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by The Steel Co Glasgow 29/11/83

James Webb
 Surveyor, Lloyd's Register,
 Glasgow