

16 NOV. 83

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office.

TESTS OF BOILER STEEL.

Tests of 6 Steel plates manufactured by The Steel Co of Scotland of Blackburn, Glasgow
for Boilers No. 308/9 to be constructed by Messrs M. Paul & Co of Dumbarton
for J. S. 4229 Burrell & Co

Date first visit last visit 10/11/83 No. of Visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ sample as set forth below, and the temper and bending tests _____ as required by Circular No 438

Then a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	Firebox	D471		4358	.39	1.17	.456	12.65	27.7	27.	The remainder of the plate, advised were tested by the Steel Co. The result stamped upon each plate.

© 2021

D. J.
16/11/19

Fee £ : :

Expenses £ : :

£ : :

To be paid by *The Steel* (2)

Surveyor, Lloyd's Register,

Glasgow

1571/13