

Glasgow Report No 6485.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

LLOYD'S REGISTER OF SHIP
RECEIVED
20 OCT. 83
LOI

No. 1323

(Received in London Office)

TESTS OF BOILER STEEL.

Tests of ~~5~~ Steel plates manufactured by The Steel Co^o of Scotland of Blochairn, Glasgow for Boiler No. 106 to be constructed by J. J. Thomson of Glasgow for ✓

Date first visit _____ last visit 11/10/83 No. of Visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests as required by Circular No 438

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose. Dimensions	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	2 1/2" x 1/16"	L432		A912	.69	1.16	.800	22.6	28.2	21.5	The remainder of the plates advised, were tested by the Steel Co & the results stamped upon each plate.
				JM							

JM 20/10/83

Fee £ : :
Expenses £ : :
£ : :

To be paid by The Steel Co^o Glasgow 19/10/83

© 2021
James Webb
Surveyor, Lloyd's Register
Foundation

7000-102579
GLS201-0007

J. J. Throssing, Jr.
186
Moles



© 2021

Lloyd's Register
Foundation