



No. 2628.

(Received at London Office, ...)

TESTS OF BOILER STEEL.

Tests of 1 Steel Plate manufactured by Messrs J. Colville & Sons of Motherwell
 for Boiler No. 88 to be constructed by Messrs Muir & Houston of Glasgow
 for Messrs Scott & Co. S. J. No. 59.

Date first visit May 12th 1885 last visit _____ No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from
 _____ charges. The tensile test has been applied to 1 sample as set forth below,
 and the temper and bending tests as required by Circular No. 438.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons. J		
1	Comb. Cham. Cen. Side	J 382		2103	.43	1.4	6.02	17.52	29.1	24.5	

Fee £ : : :
 Expenses £ : : :
 £ : : :

To be paid by _____



© 2020
H. M. Dowd R.S. 85
 Surveyor, Lloyd's Register
 Glasgow 27.5.85