

Glasgow Report No. 4114

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office.)

No. 2584



TESTS OF BOILER STEEL.

Tests of *P* Steel Plate manufactured by Messrs D. Colville & Sons of Motherwell for Boiler No. 322 to be constructed by Messrs D. W. Henderson & Co. of Glasgow for

Date first visit May 1st 1885 last visit _____ No. of Visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests as required by Circular No. 438

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Back Top	2815		7946	.74	1.48	1.095	31.74	29.0	27.5	M 13/5/85

Fee £ : :
 Expenses £ : :
 £ : : _____

To be paid by _____



© 2021

H. M. Dool
 Surveyor, Lloyd's Register,

Glasgow
 P. 5. B.