

Glasgow Report No. 4144

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING



No. 2462.

(Received in London Office,

TESTS OF BOILER STEEL.

Tests of 4 Steel Plates manufactured by Messrs D Colville & Sons of Motherwell for Boiler No. 322 to be constructed by Messrs D W Henderson & Co of Glasgow for their S.S. No.

Date first visit June 5th 1885 last visit No. of visits

The specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests as required by Circular No. 438.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Comb. Churn Side Jub 2			653	.58	1.33	.771	21.54	27.9	28.5	

Fee £ : :
 Expenses £ : :
 £ : : To be paid by



H. D. Dove
 Surveyor, Lloyd's Register,

Glasgow
 27.85

D.S.
 1/7/85