

Glasgow Report No. 2984

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 2984.

(Received at London Office,

TESTS OF BOILER STEEL.

Tests of 7 Steel Plates manufactured by Messrs D. Colville & Sons of Motherwell for Boiler No. _____ to be constructed by Messrs Barclay Curle & Co. of Glasgow for the S.S. "Cowlund"

Date first visit Oct 6th 1885 last visit _____ No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests as required by Circular No. 438.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brlth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	6.8 x 26 x 3/8	H812		1758	.37	1.48	547	15.10	27.6	23.0	

D. J. 17/10/85

Fee £ : :
 Expenses £ : :
 £ : : _____

To be paid by _____



© 2021
A. N. Dove
 Surveyor, Lloyd's Register.
Glasgow
15.10.85