

(Received at London Office

PING. RECEIVED
 20 OCT. 85

Tests of 6 Steel Plates manufactured by Messrs Colville & Sons of Motherwell
for Boiler No. 1 to be constructed by Messrs Barclay & Co of Glasgow
for the S.S. Courland.

Date first visit *Sept. 11. 1885* last visit No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ sample as set forth below, and the temper and bending tests *as required by Circular M 458.*

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	5-3 x 6 1/4 x 7/16	H/93		2430	.43	1.73	.742	21.89	29.4	20	

D.G.
 30/10/19

D.G.
30/10/85

Fee £ : :

Expenses £ : :

£ : :

To be paid by

Surveyor, Lloyd's Register.

Glasgow
28.10.83