

Glasgow Report No. 4319 + 4161

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

(Received at London Office)

No. 2981



TESTS OF BOILER STEEL.

Tests of 4 Steel Bars manufactured by Messrs J Colville & Sons of Motherwell for Boiler No. 399/400 to be constructed by Messrs R. Napier & Sons of Glasgow for their S.S. No. 399/400.

Date first visit Sep. 22^d 1885 last visit _____ No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests as required by Circular No. 438

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Br.lth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Angle Bar 4 x 3 1/2 x 1/4	M614		1343	52	1.77	.92	24.95	27.1	30.0	

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by



© 2021

George Harrison
 Surveyor, Lloyd's Register.

Lloyd's Register
 Foundation
 Glasgow

9-10-85