

(Received at London Office

Tests of 7 Steel Plate manufactured by Messrs D. Colville & Sons of Motherwell  
for Boiler No. 299 to be constructed by Messrs A. Stephen & Sons of Glasgow  
for their J.S. No. 299

Date first visit Jan 22<sup>nd</sup> 1886 last visit \_\_\_\_\_ No. of visits \_\_\_\_\_

The \_\_\_\_\_ specified in the accompanying copy of Advice Notes were rolled from \_\_\_\_\_ charges. The tensile test has been applied to \_\_\_\_\_ samples as set forth below, and the temper and bending tests ~~to a shearing from each plate~~

15/4/86

<i>Fee</i> . . . . .	£	:	:
<i>Expenses</i> £	:	:	
	£	:	:

*To be paid by*

© 2021  
H. H. Hone  
Surveyor, Lloyd's Register.  
Clayton  
10286

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.