

S. S. Landaura "Glasgow Report No. 4493"

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING



No. 2892.

(Received at London Office)

TESTS OF BOILER STEEL.

Tests of 2 Steel Plates manufactured by Messrs D Colville & Sons of Motherwell for Boiler No. 300 to be constructed by Messrs Denny & Co. of Dumbarton for Messrs W. Denny & Bros S. S. No. 307

Date first visit July 17th 1885 last visit _____ No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests as required by Circular No. 438*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	4.4 1/2 Rad x 43 1/2 x 16	707		428	.95	1.51	1.434	40.11	27.2	29.0	

D.P. 7/9/85

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by _____



© 2021 Andrew
 Surveyor, Lloyd's Register
 Glasgow
 4.9.85

[T. & Son - 6000 - 5/5/85.]