

Tests of 2 Steel Plates manufactured by The Steel Co. of Scotland of Lochairn
for Boiler No. 125 to be constructed by Messrs J. & J. Thomson of Glasgow
for S.S. No. 134 building by Messrs Aitken & Mansell

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ samples as set forth below, and the temper and bending tests Satisfactory

12/12/87

£ : :

© 2021

Surveyor, Lloyd's Register,
Glasgow