

S. S. Magul Glasgow Report No. 8194.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

(Received at London Office)

No. ~~7904~~ 50



TESTS OF BOILER STEEL.

Tests of 1 Steel plate manufactured by The Steel Co. of Scotland of Glasgow  
 for Boiler No. 125 to be constructed by Messrs J. & J. Thomson of Glasgow  
 for the S.S. No. 134 building by Messrs Ratten and Mansell  
 Date first visit 27/5 last visit No. of visits 1

The specified in the accompanying copy of Advice Notes were rolled from  
 charges. The tensile test has been applied to 1 sample as set forth below,  
 and the temper and bending tests Satisfactory

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	Tube plate	G. 143		9011	.9	1.17	1053	29.9	28.3	24.5	

B.P.  
8/6/87

Fee ..... £ : :  
 Expenses £ : :  
 £ : :

To be paid by

J. D. Roberts  
 Surveyor, Lloyd's Register.  
 Glasgow  
 2/6/87  
 Lloyd's Register Foundation

*John J. Thomson's*  
*No. 125 - B.*



© 2021

Lloyd's Register  
Foundation