

S.S. "Victoria" Glasgow Report No. 8195.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

(Received in London Office)

No. 4649



TESTS OF BOILER STEEL.

Tests of 16 Steel Plates manufactured by Messrs D Colville & Sons of Motherwell for Boiler No. 307 to be constructed by Messrs A Stephen & Sons of Glasgow for their S.S. No. 307.

Date first visit April 7th 1887 last visit April 11th 1887 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests to a shearing from each plate

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	6.4 1/2 x 35 x 17/32	V33		1306	.53	1.53	.811	22.27	27.4	24.5	
2	18.37 1/2 x 4.10 1/2 x 8 x 1/16	G205		1722	1.07	1.56	1.669	46.80	27.4	25.0	

DP
21/4/87

Fee £ : :

Expenses £ : :

£ : : To be paid by

© 2021

 H.M. Dove,
 Surveyor, Lloyd's Register,
 Glasgow
 14.4.87