


S.S. "Victoria" Glasgow Report No. 8195

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

No. 4934

(Received at London Office)



**TESTS OF BOILER STEEL.**

Tests of 29 Steel *bars* manufactured by *The Steel Co. of Scotland* of *Newton* for Boiler No. *207* to be constructed by *A. Stephen Esq.* of *Glasgow* for ✓

Date first visit *11/5/87* last visit *16/5/87* No. of visits ✓

The ✓ specified in the accompanying copy of Advice Notes were rolled from ✓ charges. The tensile test has been applied to *4* samples as set forth below, and the temper and bending tests *applied to piece of each length with satisfactory results.*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	<i>Stay bars</i>			<i>579</i>	<i>1.18</i>	<i>dia 1.094</i>	<i>32.4</i>	<i>29.6</i>	<i>32.0</i>		
				<i>650</i>	<i>1.18</i>	<i>" 1.094</i>	<i>32.2</i>	<i>29.4</i>	<i>26.5</i>		
				<i>520</i>	<i>1.2</i>	<i>" 1.13</i>	<i>32.1</i>	<i>28.4</i>	<i>30.0</i>		
				<i>697</i>	<i>1.28</i>	<i>" 1.496</i>	<i>42.8</i>	<i>28.6</i>	<i>31.0</i>		

*W.P. 26/5/87*

Fee ..... £ : :  
 Expenses £ : :  
 £ : : \_\_\_\_\_

To be paid by



© 2021  
*A. Kaul*  
 Surveyor, Lloyd's Register  
*Glasgow*  
*20/5/87*