

Tests of 8 Steel plates manufactured by Messrs. N. Beardmore & Co. of Parkhead for Boiler No. 258 to be constructed by Messrs. N. Simon & Co. of Renfrew for the S.S. No. 258 building by the same firm

Date first visit 9th Feb. last visit 13th Feb. No. of visits Constant attendance.

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests applied to piece cut off each plate with satisfactory results -

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Description	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	10.8 x 6 1/4 x 3/16	M 29	113	94	1.26	1.184	33.8	28.5	25.0		
	10.10 x 6 1/4 x 3/16	M 27	972	93	1.17	1.088	32.5	29.8	21.5		

D.F. 15/2/88

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

© 2021

Wm. Johnston

Surveyor, Lloyd's Register

Glasgow 13/2/88

GLS210-0082