


Glasgow Report No. 8848.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 8003

(Received at London Office)



TESTS OF BOILER STEEL.

Tests of 14 Steel bars manufactured by The Steel Co^{ys} of Scotland of Newby Govan for Boiler No. 400/1 to be constructed by Messrs Hop & Duross of Glasgow for P. S. "Veloxy."

Date first visit 21-6-88 last visit 27-6-88 No. of visits ✓

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests applied to pieces from two bars, with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Stay bars 1 3/4 dia	M178		586	1.17 dia	1.075	30.9	28.7	31.5		
2	" " 1 3/8 dia	A158		853	1.36	1.452	40	27.5	34		

RF 4/1/89

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by



W. Vibey
 Surveyor, Lloyd's Register.

© 2021
 Lloyd's Register
 Foundation
 Glasgow

28-6-88