


No. 6592

(Received at London Office,

TESTS OF BOILER STEEL.

Tests of 2 Steel Plate manufactured by Messrs DeLorville & Sons of Motherwell
 for Boiler No. 344.5 to be constructed by Messrs W. King & Co of Glasgow
 for Messrs Workman Clark & Co's S.S. No. 55456.



Date first visit February 21st 1888 last visit February 23rd 1888. No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	13.7 x 7 1/2 x 1 3/8	G501		5392	1.19	1.05	1.249	36.23	29.0	26.0	

DP 25/2/88

Fee £ : :
 Expenses £ : :
 £ : : _____

To be paid by _____

© 2021
 H. W. Dove.
 Surveyor, Lloyd's Register,
 Glasgow
 23-2-88