


No. 6658

(Received at London Office)



TESTS OF BOILER STEEL.

Tests of 3 Steel Plate manufactured by Messrs D Colville & Sons of Motherwell for Boiler No. 344.5 to be constructed by Messrs W. King & Co of Glasgow for Messrs Workman Clark & Co S. N. 55/6.

Date first visit February 23rd 1888 last visit February 27th 1888 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Shell Plate	£815		5892	1.20	1.05	1.296	36.94	28.5	25.0	

*DP
29/2/88*

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

H. M. Dove
 Surveyor, Lloyd's Register,
 Glasgow
27-2-88