

(Received at London Office

Tests of 4 Steel Plates manufactured by Messrs D Colville & Sons of Motherwell
for Boiler No. 344.5 to be constructed by Messrs W. & A. R. & Co of Glasgow
for Messrs Workman Clark & Co. S.S. No 58/56. 1

Date first visit March 26th 1888 last visit March 28th 1888 No. of visits.

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ samples as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results.

6. 4. 88

£ : :

To be paid by

Surveyor, Lloyd's Register,

30-3.58