


No. 4332

(Received at London Office)



TESTS OF BOILER STEEL.

Tests of 3 Steel Plates manufactured by Messrs D. Cobille & Sons of Motherwell for Boiler No. 344.5 to be constructed by Messrs W. King & Co of Glasgow for Messrs Workman Clark & Co. S.S. No. 55/b

Date first visit April 17th 1888 last visit April 19th 1888 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from the plate with satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	3.9 x 42 x 3/4	297		2013	.77	1.87	1.439	40.70	28.2	28.0	

Fee £ : :

Expenses £ : :

£ : :

To be paid by



© 2021
 H. M. Dove
 Surveyor, Lloyd's Register
 Glasgow
 19-4-88