

S.S. "Kirklands" Glasgow Report No. 8862.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 4464

(Received at London Office, _____)

TESTS OF BOILER STEEL.

Tests of 1 Steel Plate manufactured by Messrs O'Colville Bros of Motherwell
for Boiler No. 3445 to be constructed by Messrs W. King & Co of Glasgow
for Messrs Workman Clark & Co S.S. No. 53/6

Date first visit April 20th 1888 last visit May 2nd 1888 No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from
charges. The tensile test has been applied to 1 samples as set forth below,
and the temper and bending tests to a shearing from the plate with
satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	Knees for Bottom of Ber	M 444		5771	1.01	1.17	1.181	33.07	28.0	20.5	

Fee £ : :

Expenses £ : :

£ : :

To be paid by _____

A. M. Done.
Surveyor, Lloyd's Register.

Glasgow