

S.S. Lady Martin Glasgow Report No. 8899  
 No. 4841

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received at London Office, 18 JUN 88)

TESTS OF BOILER STEEL.

Tests of 28 Steel Plate manufactured by Messrs D. Colville & Sons of Motherwell for Boiler No. 87 to be constructed by Messrs Dunsmin & Jackson of Glasgow for Messrs Workman Clark & Co. S.S. No. 60

Date first visit June 11<sup>th</sup> 1888 last visit June 14<sup>th</sup> 1888 No. of visits

The \_\_\_\_\_ specified in the accompanying copy of Advice Notes were rolled from \_\_\_\_\_ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brlth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Cylinder stays	A533		3314	1.13	1.13	1.276	38.35	30.0	25.0	W.M.D.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

Fee ..... £ : :  
 Expenses £ : :  
 £ : :

To be paid by

© 2021  
 A. M. Done  
 Surveyor, Lloyd's Register  
 Glasgow  
 15.6.88