

LLOYD'S REGISTER  
 P  
 21 SEP 88

**TESTS OF BOILER STEEL.**

Tests of 1 Steel Plate manufactured by Messrs J. Colville & Sons of Motherwell  
 for Boiler No. 87 to be constructed by Messrs James Dunlop & Co. of Glasgow  
 for Messrs Workman Clark & Co. S.S. No. 60

Date first visit Sept. 14<sup>th</sup> 1888 last visit Sept. 19<sup>th</sup> 1888 No. of visits

The \_\_\_\_\_ specified in the accompanying copy of Advice Notes were rolled from \_\_\_\_\_ charges. The tensile test has been applied to 1 samples as set forth below and the temper and bending tests to a shearing from the plate with Satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	5.6 x 34 + $\frac{19}{32}$	A623		2950	.56	1.67	.935	26.76	28.6	24.0	Ad

Fee ..... £ : :  
 Expenses £ : :  
 £ : : To be paid by

© 2021  
  
 H. M. Dow  
 Surveyor, Lloyd's Register,  
 Glasgow  
 19.9.88  
 GLSR12-0038