



ADDRESS FOR TELEGRAMS, "MACMILLAN," DUMBARTON.

TELEPHONE N° 4.

ARCHD. MACMILLAN & SON, LTD.

Shipbuilders.

Dock Yard.

Dumbarton, 24<sup>th</sup> Nov. 1894.

Messrs Lloyd's Surveyors  
Glasgow.

Dear Sirs,

Referring to your Mr. Thearle's verbal communication regarding deficiency in weight of cables and steam chain for our #331, we communicated with the makers, Messrs H. P. Parker & Co., and on Wednesday last we had a visit from their Manager, Mr. Rubery, who informed us that the length of the cables and chain, and the sizes of the links, were in strict accordance with the requirements of your rules, and that the slight deficiency was partly due to the weight of material in the cast iron studs, and also to the absence of one shackle, which we understand is included in your weights.

Seeing that the sizes of cables conform to

G-LS246-0003



your rules and that they have been delivered  
into our works, we trust your Committee  
will see their way to pass them in  
this instance.

We are  
Yours faithfully

FOR ARCHD. McMILLAN & SON, LONDON.  
Alex. W. Kennedy  
MANAGER.

The certificates are returned herewith.



© 2021

Lloyd's Register  
Foundation