

S. S. Moskwa

This vessel was recently classed.

Since the case was before the Committee the vessel has had some further steam trials and at one of them a slight leakage took place from the L P cylinder. The cracks in the casting have now been repaired.

The matter is of very little moment, but the vessel being new the Surveyor has reported upon it for the Committee's information.

The owners approve of the repairs executed.

It is submitted that the vessel is eligible to remain as classed without further notation.

J. L. W.

25/10/98

To remain as classed
(See 125th Annual Report)



© 2021

Lloyd's Register
Foundation

GLS270-0071