

Are all connections with the sea direct on the skin of the ship

Yes.

Are they Valves or Cocks

None.

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates

Yes.

Are the discharge pipes above or below the

S. S. Dunbar

Submitted the Surveyor be
requested to give the dates
of test of the main boilers.

As to 13/1700

GLS292-0032



12.12.00

© 2019

12.12.00

Lloyd's Register
Foundation

S. Deighton's Material Steel

length of plain part top bottom 4'9" Thickness of plates crown bottom 1/32"

Description of longitudinal joint

Weld.

No. of str