

Received by Chief Surveyor 12.5.00

Received from Chief Surveyor _____

SEL'S NAME Steel Steam Trawler "King Henry" Report Gms. No. 528

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	$\frac{1''}{20}$	<i>not required.</i>
Spar Sheerstrake . .		
Description of Framing:— <i>Ordinary, $\frac{1''}{20}$ thicker than required.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

The 3rd anchor is 7 lbs. less than required by Table 22, but the 2nd anchor is 2 lbs in excess.

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\pm 100 A1$ ("Steel") "Steam Trawler" as recommended.

16/8/00 $\pm 100 A1$ ("Steel")
"Steam Trawler"
1 Dk.

BK $7\frac{1}{2}$ " 3 BH. Cem. Lloyds A & C.P.
Q 18' F 21'

J. H. T.
12/5/00

C. S. J.



© 2018

Lloyd's Register
Foundation